



TITLE OR NAME	DATE	REASON	CHANGE AT	TS NO. 27	AM METER SWNH	R 214
TUNER	75.10.27	AM I. INSUFFICIENT IF DAMPING	C220 - C 222			
		AT DET				
		2. STIFF SOUND	C 223, C 225			
		3. DONOT WORK FET ABC AT ALL	R 203, R 211, D 201			
		4. POOR IMAGE REJECTION	C 205, C 236			
		5. LW TRACKING PROBLEM	C 230, C 238, C 207			
		FM I. MUTE LEVEL AT TOO HIGH	Q 105, R 137			
		INPUT				
		2. UNSTABLE STEREO MODE	R 141, R 128, R 145, D 107, D 108, D 109			
		3. BURNAL METER IS SHIFTED BY NOISE	R 105, D 110			

